


P = 0.03 кВт




Danfoss

50 Гц			i	Тип	m, кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
75	2.8	8.9	18.00	BS02-../D04LA4	3.5	600	—	90	2.35	11
62	3.2	7.8	22.00	"	"	600	—	74	2.7	9.3
50	3.6	6.9	27.00	"	"	600	—	60	3.0	8.3
41	4.15	6.0	33.00	"	"	600	—	49.5	3.45	7.2
31.5	5.6	4.3	43.00	"	"	600	—	38	4.65	5.2
25	6.5	3.4	54.00	"	"	600	—	30	5.4	4.1
19.5	7.4	2.7	70.00	"	"	600	—	23.5	6.2	3.2
15	12.4	3.1	90.00	BS04-../D04LA4	3.9	1000	—	18	10.3	3.7
14.5	11.6	3.3	93.92	"	"	1000	—	17.5	9.6	4.0
13.5	13.5	2.8	102.9	"	"	1000	—	16	11.4	3.3
12	13.6	2.8	117.0	"	"	1000	—	14	11.6	3.3
11	16.4	2.5	123.0	"	"	1000	—	13.5	13.3	3.1
9.8	18.1	2.3	138.4	"	"	1000	—	12	14.8	2.8
9.0	17.5	2.2	150.3	"	"	1000	—	11	14.3	2.7
8.5	20.5	1.8	160.1	"	"	1000	—	10.5	16.6	2.2
7.8	19.8	2.0	174.0	"	"	1000	—	9.4	16.4	2.4
6.2	24	1.65	220.0	"	"	1000	—	7.4	20.5	1.95
5.4	27.5	1.5	251.6	"	"	1000	—	6.5	22.5	1.8
4.5	32	1.35	300.7	"	"	1000	—	5.4	27	1.6
4.0	35.5	1.25	338.3	"	"	1000	—	4.8	29.5	1.5
3.5	40	1.15	391.3	"	"	1000	—	4.2	33	1.35
5.4	30.5	3.2	252.0	BS06-../D04LA4	8.4	2000	—	6.5	25.5	3.9
4.3	37.5	2.8	315.3	"	"	2000	—	5.2	31	3.4
3.8	42	2.6	358.9	"	"	2000	—	4.6	34.5	3.2
3.3	47.5	2.3	418.0	"	"	2000	—	3.9	40	2.8
2.5	67	2.8	544.8	BS10Z-../D04LA4	21	6000	—	3.0	56	3.4
2.2	72	2.6	638.7	"	"	6000	—	2.6	61	3.1
1.8	85	2.1	788.7	"	"	6000	—	2.1	73	2.5
1.5	101	1.55	905.6	"	"	6000	—	1.8	84	1.9

P = 0.04 кВт

127	2.45	10	10.67	BS02-../D04LA4	3.5	600	—	152	2.05	12
100	2.95	8.5	13.50	"	"	600	—	120	2.45	10
75	3.75	6.7	18.00	"	"	600	—	90	3.1	8.1
62	4.3	5.8	22.00	"	"	600	—	74	3.6	6.9
50	4.8	5.2	27.00	"	"	600	—	60	4.0	6.3
41	5.5	4.5	33.00	"	"	600	—	49.5	4.6	5.4
31.5	7.5	3.2	43.00	"	"	600	—	38	6.2	3.9
25	8.7	2.5	54.00	"	"	600	—	30	7.2	3.1
19.5	9.9	2.0	70.00	"	"	600	—	23.5	8.2	2.4
22	11.6	3.3	61.50	BS04-../D04LA4	3.9	1000	—	26.5	9.6	4.0
21.5	11.1	3.2	64.06	"	"	1000	—	25.5	9.4	3.8
19	13.2	2.9	71.18	"	"	1000	—	23	10.9	3.5
18	12.9	2.9	77.00	"	"	1000	—	21.5	10.8	3.5
15	16.5	2.3	90.00	"	"	1000	—	18	13.7	2.8
14.5	15.5	2.5	93.92	"	"	1000	—	17.5	12.8	3.0
13.5	18.1	2.1	102.9	"	"	1000	—	16	15.2	2.5
12	18.1	2.1	117.0	"	"	1000	—	14	15.5	2.5
11	21.5	1.9	123.0	"	"	1000	—	13.5	17.8	2.3
9.8	24	1.75	138.4	"	"	1000	—	12	19.7	2.1
9.0	23	1.7	150.3	"	"	1000	—	11	19.1	2.0
8.5	27	1.35	160.1	"	"	1000	—	10.5	22	1.7
7.8	26	1.55	174.0	"	"	1000	—	9.4	21.5	1.85
6.2	32.5	1.25	220.0	"	"	1000	—	7.4	27	1.5
5.4	36.5	1.1	251.6	"	"	1000	—	6.5	30.5	1.35

P = 0.04 кВт




Danfoss

50 Гц			i	Тип	m, кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
4.5	43	1.0	300.7	BS04-../D04LA4	3.9	1000	—	5.4	36	1.2
4.0	47.5	0.93	338.3	"	"	1000	—	4.8	39.5	1.1
3.5	53	0.85	391.3	"	"	1000	—	4.2	44.5	1.0
7.9	30.5	2.9	171.0	BS06-../D04LA4	8.4	2000	—	9.5	25.5	3.5
7.8	29	3.4	174.0	"	"	2000	—	9.4	24	4.1
6.2	36	2.7	220.0	"	"	2000	—	7.4	30	3.3
5.4	41	2.4	252.0	"	"	2000	—	6.5	34	2.9
4.3	50	2.1	315.3	"	"	2000	—	5.2	41.5	2.6
3.8	56	1.95	358.9	"	"	2000	—	4.6	46.5	2.4
3.3	63	1.75	418.0	"	"	2000	—	3.9	53	2.1
3.8	62	3.1	360.3	BS10Z-../D04LA4	21	6000	—	4.5	52	3.7
3.2	72	2.6	432.4	"	"	6000	—	3.8	61	3.1
2.5	90	2.1	544.8	"	"	6000	—	3.0	75	2.5
2.2	97	1.95	638.7	"	"	6000	—	2.6	82	2.3
1.8	114	1.6	788.7	"	"	6000	—	2.1	98	1.85
1.5	134	1.2	905.6	"	"	6000	—	1.8	112	1.4
1.8	114	2.7	763.4	BS20Z-../D04LA4	32	8000	—	2.2	93	3.3

P = 0.06 кВт

295	1.7	8.8	4.60	BS02-../D04LA4	3.5	450	—	355	1.42	11
250	2.0	10	5.40	"	"	510	—	300	1.68	12
200	2.45	10	6.75	"	"	590	—	240	2.05	12
164	2.9	8.6	8.25	"	"	600	—	197	2.4	10
127	3.65	6.8	10.67	"	"	600	—	152	3.05	8.2
100	4.45	5.6	13.50	"	"	600	—	120	3.7	6.8
75	5.6	4.5	18.00	"	"	600	—	90	4.7	5.3
62	6.4	3.9	22.00	"	"	600	—	74	5.4	4.6
50	7.2	3.5	27.00	"	"	600	—	60	6.0	4.2
41	8.3	3.0	33.00	"	"	600	—	49.5	6.9	3.6
31.5	11.2	2.1	43.00	"	"	600	—	38	9.3	2.6
25	13	1.7	54.00	"	"	600	—	30	10.8	2.0
19.5	14.9	1.35	70.00	"	"	600	—	23.5	12.4	1.6
18	16.2	2.5	75.00	BS03-../D05LA4	5.4	800	—	22	13.2	3.0
35.5	11.1	3.3	38.42	BS04-../D04LA4	3.9	1000	—	42.5	9.3	4.0
28.5	13.6	2.8	47.86	"	"	1000	—	34	11.4	3.3
22	17.4	2.2	61.50	"	"	1000	—	26.5	14.4	2.6
21.5	16.7	2.2	64.06	"	"	1000	—	25.5	14.1	2.6
19	19.9	1.9	71.18	"	"	1000	—	23	16.4	2.3
18	19.4	1.95	77.00	"	"	1000	—	21.5	16.2	2.3
15	24.5	1.55	90.00	"	"	1000	—	18	20.5	1.85
14.5	23	1.65	93.92	"	"	1000	—	17.5	19.3	1.95
13.5	27	1.4	102.9	"	"	1000	—	16	22.5	1.7
12	27	1.4	117.0	"	"	1000	—	14	23	1.65
11	32.5	1.25	123.0	"	"	1000	—	13.5	26.5	1.55
9.8	36	1.15	138.4	"	"	1000	—	12	29.5	1.4
9.0	35	1.1	150.3	"	"	1000	—	11	28.5	1.35
8.5	41	0.9	160.1	"	"	1000	—	10.5	33	1.1
7.8	39.5	1.0	174.0	"	"	1000	—	9.4	32.5	1.25
6.2	48.5	0.82	220.0	"	"	1000	—	7.4	41	0.98
11.5	32	2.9	118.8	BS06-../D04LA4	8.4	2000	—	14	26.5	3.5
10.5	36.5	2.8	129.0	"	"	2000	—	13	29.5	3.5
9.5	38.5	2.5	142.2	"	"	2000	—	11.5	31.5	3.1
9.2	40	2.7	146.8	"	"	2000	—	11.5	32	3.3

P = 0.06 кВт




Danfoss

50 Гц			i	Тип	m, кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
7.9	46	1.9	171.0	BS06-../D04LA4	8.4	2000	—	9.5	38.5	2.3
7.8	44	2.2	174.0	"	"	2000	—	9.4	36.5	2.7
6.2	54	1.8	220.0	"	"	2000	—	7.4	45.5	2.2
5.4	61	1.6	252.0	"	"	2000	—	6.5	51	1.95
4.3	75	1.4	315.3	"	"	2000	—	5.2	62	1.7
3.8	84	1.3	358.9	"	"	2000	—	4.6	69	1.6
3.3	95	1.15	418.0	"	"	2000	—	3.9	80	1.4
11.5	36.5	3.3	119.6	BS10-../D06LA4	23	6000	—	14	30	4.0
10.5	34.5	4.8	130.3	"	"	6000	—	12.5	29	5.7
8.9	41	4.0	152.7	"	"	6000	—	11	33	5.0
7.2	50	3.4	188.6	"	"	6000	—	8.6	42.5	4.0
6.3	58	3.1	216.6	"	"	6000	—	7.5	48.5	3.7
5.4	67	2.7	254.0	BS10Z-../D06LA4	25	6000	—	6.4	57	3.2
4.5	78	2.4	302.5	"	"	6000	—	5.4	65	2.9
3.8	93	2.0	360.3	"	"	6000	—	4.5	78	2.4
3.2	109	1.75	432.4	"	"	6000	—	3.8	91	2.1
2.5	135	1.4	544.8	"	"	6000	—	3.0	112	1.7
2.2	145	1.3	638.7	"	"	6000	—	2.6	123	1.55
1.8	171	1.05	788.7	"	"	6000	—	2.1	147	1.2
3.2	109	3.0	430.8	BS20Z-../D06LA4	35	8000	—	3.8	91	3.6
2.6	121	3.0	539.7	"	"	8000	—	3.1	101	3.6
2.2	140	2.4	619.2	"	"	8000	—	2.7	114	2.9
1.8	171	1.8	763.4	"	"	8000	—	2.2	140	2.2
1.7	195	2.4	804.1	BS30Z-../D06LA4	54	10000	—	2.1	158	3.0
1.5	215	2.1	932.0	"	"	10000	—	1.8	181	2.5
1.5	225	3.3	908.2	BS40Z-../D06LA4	68	15000	—	1.8	187	4.0

P = 0.09 кВт

295	2.55	5.9	4.60	BS02-../D04LA4	3.5	450	—	355	2.1	7.1
250	3.0	6.7	5.40	"	"	510	—	300	2.5	8.0
200	3.65	6.8	6.75	"	"	590	—	240	3.05	8.2
164	4.4	5.7	8.25	"	"	600	—	197	3.65	6.8
127	5.5	4.5	10.67	"	"	600	—	152	4.6	5.4
100	6.7	3.7	13.50	"	"	600	—	120	5.5	4.5
75	8.4	3.0	18.00	"	"	600	—	90	7.0	3.6
62	9.7	2.6	22.00	"	"	600	—	74	8.1	3.1
50	10.8	2.3	27.00	"	"	600	—	60	9.0	2.8
41	12.5	2.0	33.00	"	"	600	—	49.5	10.4	2.4
31.5	16.9	1.4	43.00	"	"	600	—	38	14	1.7
25	19.5	1.15	54.00	"	"	600	—	30	16.3	1.35
19.5	22	0.91	70.00	"	"	600	—	23.5	18.6	1.1
27	18.4	3.0	50.00	BS03-../D05LA4	5.4	800	—	32.5	15.3	3.6
22	20.5	2.3	62.00	"	"	800	—	26.5	17.1	2.8
18	24	1.65	75.00	"	"	800	—	22	19.9	2.0
56	11.6	2.9	24.25	BS04-../D04LA4	3.9	1000	—	67	9.7	3.5
52	11.7	3.2	26.21	"	"	1000	—	62	9.8	3.9
43	13.9	2.7	31.50	"	"	1000	—	52	11.5	3.3
35.5	16.7	2.2	38.42	"	"	1000	—	42.5	13.9	2.7
28.5	20.5	1.85	47.86	"	"	1000	—	34	17.1	2.2
22	26	1.45	61.50	"	"	1000	—	26.5	21.5	1.75
21.5	25	1.45	64.06	"	"	1000	—	25.5	21	1.7
19	29.5	1.3	71.18	"	"	1000	—	23	24.5	1.55
18	29	1.3	77.00	"	"	1000	—	21.5	24	1.6



Danfoss

P = 0.09 кВт


50 Гц			i	Тип	m, кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
15	37	1.05	90.00	BS04-../D04LA4	3.9	1000	—	18	31	1.25
14.5	34.5	1.1	93.92	"	"	1000	—	17.5	28.5	1.35
13.5	40.5	0.94	102.9	"	"	1000	—	16	34	1.1
12	40.5	0.94	117.0	"	"	1000	—	14	34.5	1.1
11	49	0.84	123.0	"	"	1000	—	13.5	40	1.05
21.5	27	3.0	64.06	BS06-../D04LA4	8.4	2000	—	25.5	22.5	3.6
19	32	2.9	71.18	"	"	2000	—	23	26.5	3.5
18	31.5	2.7	77.00	"	"	2000	—	21.5	26.5	3.2
15	40	2.5	90.00	"	"	2000	—	18	33	3.0
13.5	43.5	2.3	103.1	"	"	2000	—	16	37	2.7
11.5	48.5	1.95	118.8	"	"	2000	—	14	39.5	2.4
10.5	54	1.95	129.0	"	"	2000	—	13	44	2.4
9.5	57	1.7	142.2	"	"	2000	—	11.5	47.5	2.1
9.2	60	1.75	146.8	"	"	2000	—	11.5	48.5	2.2
7.9	69	1.3	171.0	"	"	2000	—	9.5	57	1.55
7.8	66	1.5	174.0	"	"	2000	—	9.4	54	1.8
6.2	81	1.2	220.0	"	"	2000	—	7.4	68	1.45
5.4	92	1.1	252.0	"	"	2000	—	6.5	76	1.3
4.3	113	0.94	315.3	"	"	2000	—	5.2	94	1.15
3.8	126	0.87	358.9	"	"	2000	—	4.6	104	1.05
11.5	55	2.2	119.6	BS10-../D06LA4	23	6000	—	14	45	2.7
10.5	52	3.2	130.3	"	"	6000	—	12.5	44	3.7
8.9	61	2.7	152.7	"	"	6000	—	11	50	3.3
7.2	76	2.2	188.6	"	"	6000	—	8.6	63	2.7
6.3	87	2.1	216.6	"	"	6000	—	7.5	73	2.5
5.4	101	1.8	254.0	BS10Z-../D06LA4	25	6000	—	6.4	85	2.1
4.5	118	1.6	302.5	"	"	6000	—	5.4	98	1.95
3.8	140	1.35	360.3	"	"	6000	—	4.5	118	1.6
3.2	163	1.15	432.4	"	"	6000	—	3.8	137	1.4
2.5	200	0.95	544.8	"	"	6000	—	3.0	169	1.1
2.2	215	0.88	638.7	"	"	6000	—	2.6	185	1.05
6.0	91	3.2	225.6	BS20-../D06LA4	34	8000	—	7.2	76	3.8
5.3	103	2.9	257.8	BS20Z-../D06LA4	35	8000	—	6.3	87	3.4
4.5	120	2.5	300.1	"	"	8000	—	5.4	100	3.0
3.8	140	2.3	359.9	"	"	8000	—	4.6	115	2.8
3.2	163	2.0	430.8	"	"	8000	—	3.8	137	2.4
2.6	181	2.0	539.7	"	"	8000	—	3.1	152	2.4
2.2	210	1.55	619.2	"	"	8000	—	2.7	171	1.95
1.8	255	1.2	763.4	"	"	8000	—	2.2	210	1.5
3.8	167	2.4	359.6	BS30Z-../D06LA4	54	10000	—	4.6	138	2.9
3.5	159	3.7	390.2	"	"	10000	—	4.2	133	4.4
3.0	183	3.3	457.3	"	"	10000	—	3.6	152	3.9
2.6	210	2.9	539.3	"	"	10000	—	3.1	177	3.4
2.1	245	2.4	651.0	"	"	10000	—	2.5	205	2.8
1.7	290	1.65	804.1	"	"	10000	—	2.1	235	2.0
1.5	325	1.4	932.0	"	"	10000	—	1.8	270	1.65
1.9	270	2.8	736.5	BS40Z-../D06LA4	68	15000	—	2.2	230	3.3
1.5	335	2.2	908.2	"	"	15000	—	1.8	280	2.7

P = 0.12 кВт

295	3.4	4.4	4.60	BS02-../D04LA4	3.5	450	—	355	2.8	5.4
250	4.0	5.0	5.40	"	"	510	—	300	3.35	6.0
200	4.9	5.1	6.75	"	"	590	—	240	4.1	6.1
164	5.8	4.3	8.25	"	"	600	—	197	4.85	5.2

BAUER geared motors


P = 0.12 кВт



Danfoss

50 Гц			i	Тип	m, кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
127	7.3	3.4	10.67	BS02-../D04LA4	3.5	600	—	152	6.1	4.1
100	8.9	2.8	13.50	"	"	600	—	120	7.4	3.4
75	11.3	2.2	18.00	"	"	600	—	90	9.4	2.7
62	12.9	1.95	22.00	"	"	600	—	74	10.8	2.3
50	14.4	1.75	27.00	"	"	600	—	60	12	2.1
41	16.7	1.5	33.00	"	"	600	—	49.5	13.8	1.8
31.5	22.5	1.05	43.00	"	"	600	—	38	18.6	1.3
25	26	0.85	54.00	"	"	600	—	30	21.5	1.0
41	17	3.2	33.00	BS03-../D05LA4	5.4	800	—	49.5	14.1	3.9
35	20.5	2.7	39.00	"	"	800	—	42	17.4	3.2
27	24.5	2.2	50.00	"	"	800	—	32.5	20	2.8
22	27.5	1.75	62.00	"	"	800	—	26.5	22.5	2.1
18	32	1.25	75.00	"	"	800	—	22	26.5	1.5
83	10.6	3.3	16.31	BS04-../D04LA4	3.9	1000	—	100	8.8	4.0
65	13.3	2.8	20.96	"	"	1000	—	78	11.1	3.3
56	15.5	2.2	24.25	"	"	1000	—	67	12.9	2.6
52	15.6	2.4	26.21	"	"	1000	—	62	13.1	2.9
43	18.6	2.0	31.50	"	"	1000	—	52	15.4	2.5
35.5	22	1.7	38.42	"	"	1000	—	42.5	18.6	2.0
28.5	27	1.4	47.86	"	"	1000	—	34	22.5	1.7
22	34.5	1.1	61.50	"	"	1000	—	26.5	28.5	1.35
21.5	33.5	1.05	64.06	"	"	1000	—	25.5	28	1.3
19	39.5	0.96	71.18	"	"	1000	—	23	32.5	1.15
18	38.5	0.99	77.00	"	"	1000	—	21.5	32.5	1.15
14.5	46.5	0.82	93.92	"	"	1000	—	17.5	38.5	0.99
28	29	3.0	48.60	BS06-../D04LA4	8.4	2000	—	33.5	24.5	3.6
23.5	34.5	2.6	58.15	"	"	2000	—	28	29	3.1
21.5	36	2.2	64.06	"	"	2000	—	25.5	30.5	2.6
19	42.5	2.2	71.18	"	"	2000	—	23	35	2.7
18	42.5	2.0	77.00	"	"	2000	—	21.5	35.5	2.4
15	53	1.85	90.00	"	"	2000	—	18	44.5	2.2
13.5	58	1.7	103.1	"	"	2000	—	16	49	2.0
11.5	64	1.45	118.8	"	"	2000	—	14	53	1.75
10.5	73	1.4	129.0	"	"	2000	—	13	59	1.75
9.5	77	1.25	142.2	"	"	2000	—	11.5	63	1.55
9.2	80	1.35	146.8	"	"	2000	—	11.5	64	1.65
7.9	92	0.96	171.0	"	"	2000	—	9.5	77	1.15
7.8	88	1.1	174.0	"	"	2000	—	9.4	73	1.35
6.2	109	0.9	220.0	"	"	2000	—	7.4	91	1.1
5.4	123	0.8	252.0	"	"	2000	—	6.5	102	0.97
16.5	51	2.9	84.36	BS10-../D06LA4	23	5300	—	19.5	43	3.5
13.5	54	3.0	103.4	"	"	5600	—	16	45.5	3.5
11.5	73	1.65	119.6	"	"	6000	—	14	60	2.0
10.5	69	2.4	130.3	"	"	6000	—	12.5	58	2.8
8.9	82	2.0	152.7	"	"	6000	—	11	66	2.5
7.2	101	1.7	188.6	"	"	6000	—	8.6	85	2.0
6.3	116	1.55	216.6	"	"	6000	—	7.5	97	1.85
5.4	135	1.35	254.0	BS10Z-../D06LA4	25	6000	—	6.4	114	1.6
4.5	157	1.2	302.5	"	"	6000	—	5.4	131	1.45
3.8	186	1.0	360.3	"	"	6000	—	4.5	157	1.2
3.2	215	0.88	432.4	"	"	6000	—	3.8	183	1.05
8.5	88	3.1	159.4	BS20-../D06LA4	34	8000	—	10.5	72	3.8
7.4	102	2.7	183.0	"	"	8000	—	8.9	84	3.3
6.0	122	2.4	225.6	"	"	8000	—	7.2	101	2.9
5.3	138	2.1	257.8	BS20Z-../D06LA4	35	8000	—	6.3	116	2.5
4.5	160	1.9	300.1	"	"	8000	—	5.4	133	2.3

P = 0.12 кВт



Danfoss


50 Гц			i	Тип	m, кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
3.8	186	1.7	359.9	BS20Z-../D06LA4	35	8000	—	4.6	154	2.1
3.2	215	1.55	430.8	"	"	8000	—	3.8	183	1.8
2.6	240	1.5	539.7	"	"	8000	—	3.1	200	1.85
2.2	280	1.2	619.2	"	"	8000	—	2.7	225	1.45
1.8	340	0.91	763.4	"	"	8000	—	2.2	280	1.1
3.8	220	1.8	359.6	BS30Z-../D06LA4	54	10000	—	4.6	184	2.1
3.5	210	2.8	390.2	"	"	10000	—	4.2	177	3.3
3.0	240	2.5	457.3	"	"	10000	—	3.6	200	3.0
2.6	280	2.1	539.3	"	"	10000	—	3.1	235	2.6
2.1	325	1.8	651.0	"	"	10000	—	2.5	275	2.1
1.7	390	1.2	804.1	"	"	10000	—	2.1	315	1.5
1.5	435	1.05	932.0	"	"	10000	—	1.8	360	1.25
2.3	300	3.0	612.1	BS40Z-../D06LA4	68	15000	—	2.7	255	3.6
1.9	360	2.1	736.5	"	"	15000	—	2.2	310	2.4
1.5	450	1.65	908.2	"	"	15000	—	1.8	375	2.0

P = 0.18 кВт

295	5.1	2.9	4.60	BS02-../D05LA4	5.3	450	—	355	4.25	3.5
250	6.0	3.3	5.40	"	"	510	—	300	5.0	4.0
200	7.3	3.4	6.75	"	"	590	—	240	6.1	4.1
164	8.8	2.8	8.25	"	"	600	—	197	7.3	3.4
127	11	2.3	10.67	"	"	600	—	152	9.2	2.7
100	13.4	1.85	13.50	"	"	600	—	120	11.1	2.3
75	16.9	1.5	18.00	"	"	600	—	90	14.1	1.75
62	19.4	1.3	22.00	"	"	600	—	74	16.2	1.55
50	21.5	1.15	27.00	"	"	600	—	60	18	1.4
41	25	1.0	33.00	"	"	600	—	49.5	20.5	1.2
72	18.1	3.0	19.00	BS03-../D05LA4	5.4	800	—	86	15.1	3.6
54	21.5	2.6	25.00	"	"	800	—	65	18.2	3.0
41	25.5	2.2	33.00	"	"	800	—	49.5	21	2.6
35	31	1.75	39.00	"	"	800	—	42	26	2.1
27	36.5	1.5	50.00	"	"	800	—	32.5	30.5	1.8
22	41	1.15	62.00	"	"	800	—	26.5	34	1.4
18	48.5	0.82	75.00	"	"	800	—	22	39.5	1.0
126	10.6	3.0	10.73	BS04-../D05LA4	5.8	1000	—	151	8.8	3.6
104	12.7	2.6	13.09	"	"	1000	—	124	10.6	3.1
83	15.9	2.2	16.31	"	"	1000	—	100	13.2	2.7
65	20	1.85	20.96	"	"	1000	—	78	16.7	2.2
56	23	1.5	24.25	"	"	1000	—	67	19.4	1.75
52	23	1.65	26.21	"	"	1000	—	62	19.6	1.95
43	27.5	1.4	31.50	"	"	1000	—	52	23	1.65
35.5	33	1.1	38.42	"	"	1000	—	42.5	27.5	1.35
28.5	41	0.93	47.86	"	"	1000	—	34	34	1.1
56	24.5	3.1	24.25	BS06-../D05LA4	10	2000	—	67	20.5	3.8
52	24	3.2	26.21	"	"	2000	—	62	20	3.9
43	29	2.8	31.50	"	"	2000	—	52	24	3.3
33	37.5	2.3	41.29	"	"	2000	—	39.5	31	2.8
28	44	2.0	48.60	"	"	2000	—	33.5	36.5	2.4
23.5	51	1.8	58.15	"	"	2000	—	28	43.5	2.1
21.5	54	1.5	64.06	"	"	2000	—	25.5	45.5	1.75
19	64	1.45	71.18	"	"	2000	—	23	53	1.75
18	63	1.35	77.00	"	"	2000	—	21.5	53	1.6
15	80	1.25	90.00	"	"	2000	—	18	66	1.5
13.5	87	1.15	103.1	"	"	2000	—	16	74	1.35

BAUER geared motors

P = 0.18 кВт




Danfoss

50 Гц			i	Тип	m, кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
11.5	97	0.97	118.8	BS06-../D05LA4	10	2000	—	14	79	1.2
10.5	109	0.95	129.0	"	"	2000	—	13	88	1.2
9.5	115	0.85	142.2	"	"	2000	—	11.5	95	1.05
9.2	121	0.88	146.8	"	"	2000	—	11.5	97	1.1
28.5	45	3.2	47.59	BS10-../D06LA4	23	4050	—	34.5	37	3.9
24	53	2.8	57.12	"	"	4350	—	28.5	44.5	3.4
22.5	51	2.9	60.74	"	"	4550	—	27	42.5	3.5
19	66	2.4	71.96	"	"	5000	—	23	55	2.9
16.5	77	1.95	84.36	"	"	5300	—	19.5	65	2.3
13.5	81	2.0	103.4	"	"	5600	—	16	68	2.4
11.5	110	1.1	119.6	"	"	6000	—	14	90	1.35
10.5	104	1.6	130.3	"	"	6000	—	12.5	88	1.85
8.9	123	1.35	152.7	"	"	6000	—	11	100	1.65
7.2	152	1.1	188.6	"	"	6000	—	8.6	127	1.35
6.3	174	1.05	216.6	"	"	6000	—	7.5	146	1.25
5.4	200	0.9	254.0	BS10Z-../D06LA4	25	6000	—	6.4	171	1.05
4.5	235	0.81	302.5	"	"	6000	—	5.4	197	0.96
13.5	94	2.7	101.1	BS20-../D06LA4	34	7100	—	16.5	77	3.2
13	87	3.1	106.3	"	"	7600	—	15.5	73	3.7
11	103	2.6	127.3	"	"	8000	—	13	87	3.1
8.5	133	2.1	159.4	"	"	8000	—	10.5	108	2.5
7.4	153	1.85	183.0	"	"	8000	—	8.9	127	2.2
6.0	183	1.6	225.6	"	"	8000	—	7.2	152	1.9
5.3	205	1.45	257.8	BS20Z-../D06LA4	35	8000	—	6.3	174	1.7
4.5	240	1.25	300.1	"	"	8000	—	5.4	200	1.5
3.8	280	1.15	359.9	"	"	8000	—	4.6	230	1.4
3.2	325	1.0	430.8	"	"	8000	—	3.8	275	1.2
2.6	360	1.0	539.7	"	"	8000	—	3.1	300	1.2
6.3	180	2.9	216.4	BS30-../D06LA4	51	10000	—	7.5	151	3.4
5.2	215	2.6	261.6	BS30Z-../D06LA4	54	10000	—	6.2	182	3.1
4.5	245	2.4	306.6	"	"	10000	—	5.3	210	2.8
3.8	330	1.2	359.6	"	"	10000	—	4.6	275	1.45
3.5	315	1.85	390.2	"	"	10000	—	4.2	265	2.2
3.0	365	1.65	457.3	"	"	10000	—	3.6	305	1.95
2.6	420	1.45	539.3	"	"	10000	—	3.1	350	1.7
2.1	490	1.2	651.0	"	"	10000	—	2.5	410	1.4
1.7	580	0.82	804.1	"	"	10000	—	2.1	470	1.0
4.7	270	2.6	287.7	BS40Z-../D06LA4	68	15000	—	5.7	220	3.3
4.5	240	4.5	302.1	"	"	15000	—	5.4	200	5.4
3.8	280	3.9	356.8	"	"	15000	—	4.6	235	4.6
3.1	345	2.9	446.8	"	"	15000	—	3.7	290	3.4
2.6	415	2.7	520.8	"	"	15000	—	3.2	335	3.3
2.3	455	2.0	612.1	"	"	15000	—	2.7	385	2.4
1.9	540	1.4	736.5	"	"	15000	—	2.2	465	1.65
1.5	670	1.1	908.2	"	"	15000	—	1.8	560	1.35

P = 0.25 кВт

295	7.1	2.1	4.60	BS02-../D05LA4	5.3	450	—	355	5.9	2.5
250	8.4	2.4	5.40	"	"	510	—	300	7.0	2.9
200	10.2	2.5	6.75	"	"	590	—	240	8.5	2.9
164	12.2	2.0	8.25	"	"	600	—	197	10.1	2.5
127	15.4	1.6	10.67	"	"	600	—	152	12.8	1.95
100	18.6	1.35	13.50	"	"	600	—	120	15.5	1.6
75	23.5	1.05	18.00	"	"	600	—	90	19.6	1.3
62	26.5	0.94	22.00	"	"	600	—	74	22.5	1.1


P = 0.25 кВт



Danfoss

50 Гц			i	Тип	m, кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
50	30	0.83	27.00	BS02-../D05LA4	5.3	600	—	60	25	1.0
100	18.6	3.0	13.50	BS03-../D05LA4	5.4	800	—	120	15.5	3.5
72	25	2.2	19.00	"	"	800	—	86	21	2.6
54	30.5	1.8	25.00	"	"	800	—	65	25	2.2
41	35.5	1.55	33.00	"	"	800	—	49.5	29	1.9
35	43.5	1.25	39.00	"	"	800	—	42	36	1.55
27	51	1.1	50.00	"	"	800	—	32.5	42.5	1.3
22	57	0.84	62.00	"	"	800	—	26.5	47.5	1.0
152	12.2	2.5	8.93	BS04-../D05LA4	5.8	1000	—	182	10.2	2.9
126	14.7	2.2	10.73	"	"	1000	—	151	12.3	2.6
104	17.6	1.9	13.09	"	"	1000	—	124	14.8	2.2
83	22	1.6	16.31	"	"	1000	—	100	18.3	1.9
65	27.5	1.35	20.96	"	"	1000	—	78	23	1.6
56	32	1.05	24.25	"	"	1000	—	67	27	1.25
52	32.5	1.15	26.21	"	"	1000	—	62	27	1.4
43	38.5	0.99	31.50	"	"	1000	—	52	32	1.2
35.5	46	0.8	38.42	"	"	1000	—	42.5	38.5	0.96
82	23	3.1	16.56	BS06-../D05LA4	10	2000	—	98	19.4	3.7
69	27.5	2.7	19.82	"	"	2000	—	82	23	3.3
56	34	2.3	24.25	"	"	2000	—	67	28.5	2.7
52	33.5	2.3	26.21	"	"	2000	—	62	28	2.8
43	40.5	2.0	31.50	"	"	2000	—	52	33.5	2.4
33	52	1.65	41.29	"	"	2000	—	39.5	43.5	2.0
28	61	1.45	48.60	"	"	2000	—	33.5	51	1.75
23.5	72	1.25	58.15	"	"	2000	—	28	60	1.5
21.5	75	1.05	64.06	"	"	2000	—	25.5	63	1.25
19	89	1.05	71.18	"	"	2000	—	23	73	1.3
18	88	0.97	77.00	"	"	2000	—	21.5	74	1.15
15	111	0.88	90.00	"	"	2000	—	18	92	1.05
13.5	122	0.82	103.1	"	"	2000	—	16	102	0.98
40.5	44.5	3.0	33.55	BS10-../D06LA4	23	3550	—	48.5	37	3.6
34	52	2.7	39.96	"	"	3800	—	41	43.5	3.2
28.5	62	2.3	47.59	"	"	4050	—	34.5	51	2.8
24	73	2.1	57.12	"	"	4350	—	28.5	61	2.5
22.5	71	2.1	60.74	"	"	4550	—	27	59	2.5
19	92	1.75	71.96	"	"	5000	—	23	76	2.1
16.5	107	1.4	84.36	"	"	5300	—	19.5	90	1.65
13.5	113	1.4	103.4	"	"	5600	—	16	95	1.7
10.5	145	1.15	130.3	"	"	6000	—	12.5	122	1.35
8.9	171	0.96	152.7	"	"	6000	—	11	138	1.2
7.2	210	0.81	188.6	"	"	6000	—	8.6	177	0.96
19.5	91	3.3	70.30	BS20-../D06LA4	34	6300	—	23.5	76	3.9
18	87	3.1	76.18	"	"	6600	—	21.5	73	3.7
15.5	101	2.7	88.67	"	"	7000	—	18.5	85	3.2
13.5	130	1.9	101.1	"	"	7100	—	16.5	107	2.3
13	121	2.2	106.3	"	"	7600	—	15.5	101	2.7
11	143	1.9	127.3	"	"	8000	—	13	121	2.2
8.5	185	1.5	159.4	"	"	8000	—	10.5	150	1.85
7.4	210	1.35	183.0	"	"	8000	—	8.9	177	1.6
6.0	250	1.15	225.6	"	"	8000	—	7.2	210	1.4
5.3	285	1.05	257.8	BS20Z-../D06LA4	35	8000	—	6.3	240	1.25
4.5	330	0.91	300.1	"	"	8000	—	5.4	275	1.1
3.8	385	0.83	359.9	"	"	8000	—	4.6	320	1.0
9.0	177	3.1	151.1	BS30-../D06LA4	51	9500	—	11	145	3.7
7.3	215	2.5	186.7	"	"	10000	—	8.7	181	3.0

P = 0.25 кВт




Danfoss

50 Гц			i	Тип	m, кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
6.3	250	2.1	216.4	BS30-../D06LA4	51	10000	—	7.5	210	2.5
5.2	300	1.85	261.6	BS30Z-../D06LA4	54	10000	—	6.2	250	2.2
4.5	340	1.7	306.6	"	"	10000	—	5.3	290	2.0
3.8	460	0.86	359.6	"	"	10000	—	4.6	380	1.05
3.5	440	1.35	390.2	"	"	10000	—	4.2	365	1.6
3.0	500	1.2	457.3	"	"	10000	—	3.6	420	1.45
2.6	580	1.05	539.3	"	"	10000	—	3.1	490	1.2
2.1	680	0.85	651.0	"	"	10000	—	2.5	570	1.0
6.9	255	2.7	197.1	BS40Z-../D06LA4	68	15000	—	8.3	210	3.3
5.5	270	3.3	249.6	"	"	15000	—	6.5	230	3.9
4.7	375	1.9	287.7	"	"	15000	—	5.7	305	2.3
4.5	330	3.2	302.1	"	"	15000	—	5.4	275	3.9
3.8	395	2.7	356.8	"	"	15000	—	4.6	325	3.3
3.1	485	2.0	446.8	"	"	15000	—	3.7	405	2.4
2.6	570	1.95	520.8	"	"	15000	—	3.2	470	2.3
2.3	630	1.45	612.1	"	"	15000	—	2.7	530	1.7
1.9	750	1.0	736.5	"	"	15000	—	2.2	650	1.15
1.5	930	0.8	908.2	"	"	15000	—	1.8	780	0.95

P = 0.3 кВт

295	8.5	1.75	4.60	BS02-../D07LA4	9.3	450	—	355	7.1	2.1
250	10	2.0	5.40	"	"	510	—	300	8.4	2.4
200	12.3	2.0	6.75	"	"	590	—	240	10.2	2.5
164	14.6	1.7	8.25	"	"	600	—	197	12.2	2.0
127	18.4	1.35	10.67	"	"	600	—	152	15.4	1.6
100	22	1.15	13.50	"	"	600	—	120	18.6	1.35
75	28	0.89	18.00	"	"	600	—	90	23.5	1.05
100	22	2.5	13.50	BS03-../D07LA4	9.4	800	—	120	18.6	3.0
72	30	1.85	19.00	"	"	800	—	86	25	2.2
54	36.5	1.5	25.00	"	"	800	—	65	30	1.85
41	42.5	1.3	33.00	"	"	800	—	49.5	35	1.55
35	52	1.05	39.00	"	"	800	—	42	43.5	1.25
27	61	0.9	50.00	"	"	800	—	32.5	51	1.1
152	14.7	2.0	8.93	BS04-../D07LA4	9.8	1000	—	182	12.2	2.5
126	17.7	1.8	10.73	"	"	1000	—	151	14.7	2.2
104	21	1.55	13.09	"	"	1000	—	124	17.7	1.85
83	26.5	1.3	16.31	"	"	1000	—	100	22	1.6
65	33	1.1	20.96	"	"	1000	—	78	27.5	1.35
56	38.5	0.88	24.25	"	"	1000	—	67	32	1.05
52	39	0.97	26.21	"	"	1000	—	62	32.5	1.15
43	46.5	0.82	31.50	"	"	1000	—	52	38.5	0.99
96	24	2.8	14.07	BS06-../D07LA4	14	2000	—	116	20	3.4
82	27.5	2.6	16.56	"	"	2000	—	98	23	3.1
69	33	2.3	19.82	"	"	2000	—	82	27.5	2.7
56	40.5	1.9	24.25	"	"	2000	—	67	34	2.3
52	40	1.95	26.21	"	"	2000	—	62	33.5	2.3
43	48.5	1.65	31.50	"	"	2000	—	52	40	2.0
33	62	1.4	41.29	"	"	2000	—	39.5	52	1.65
28	73	1.2	48.60	"	"	2000	—	33.5	61	1.45
23.5	86	1.05	58.15	"	"	2000	—	28	72	1.25
21.5	90	0.89	64.06	"	"	2000	—	25.5	76	1.05
19	107	0.88	71.18	"	"	2000	—	23	88	1.05
18	106	0.8	77.00	"	"	2000	—	21.5	89	0.96
52	42.5	3.1	26.42	BS10-../D07LA4	26	3250	—	62	36	3.6

P = 0.3 кВт




Danfoss

50 Гц			i	Тип	m , кг	F _{RN} , N	F _{RV} , N	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
40.5	53	2.5	33.55	BS10-../D07LA4	26	3550	—	48.5	44.5	3.0
34	63	2.2	39.96	"	"	3800	—	41	52	2.7
28.5	75	1.95	47.59	"	"	4050	—	34.5	62	2.3
24	88	1.7	57.12	"	"	4350	—	28.5	74	2.0
22.5	85	1.75	60.74	"	"	4550	—	27	71	2.1
19	111	1.45	71.96	"	"	5000	—	23	92	1.75
16.5	128	1.15	84.36	"	"	5300	—	19.5	108	1.4
13.5	135	1.2	103.4	"	"	5600	—	16	114	1.4
10.5	174	0.94	130.3	"	"	6000	—	12.5	146	1.1
8.9	205	0.8	152.7	"	"	6000	—	11	166	0.99
23	93	3.0	58.74	BS20-../D07LA4	36	5900	—	28	76	3.7
19.5	110	2.7	70.30	"	"	6300	—	23.5	91	3.3
18	105	2.6	76.18	"	"	6600	—	21.5	87	3.1
15.5	121	2.2	88.67	"	"	7000	—	18.5	102	2.6
13.5	157	1.6	101.1	"	"	7100	—	16.5	128	1.95
13	145	1.85	106.3	"	"	7600	—	15.5	121	2.2
11	171	1.6	127.3	"	"	8000	—	13	145	1.85
8.5	220	1.25	159.4	"	"	8000	—	10.5	180	1.55
7.4	255	1.1	183.0	"	"	8000	—	8.9	210	1.35
6.0	305	0.95	225.6	"	"	8000	—	7.2	250	1.15
5.3	345	0.86	257.8	BS20Z-../D07LA4	38	8000	—	6.3	290	1.0
16.5	133	3.1	83.48	BS30-../D07LA4	54	6800	—	19.5	113	3.6
15	131	3.7	90.59	"	"	7700	—	18	109	4.5
13	149	3.4	106.2	"	"	8200	—	15.5	125	4.1
11	177	2.9	125.2	"	"	8700	—	13	149	3.5
9.0	210	2.6	151.1	"	"	9500	—	11	174	3.1
7.3	255	2.1	186.7	"	"	10000	—	8.7	215	2.5
6.3	300	1.75	216.4	"	"	10000	—	7.5	250	2.1
5.2	360	1.55	261.6	BS30Z-../D07LA4	56	10000	—	6.2	300	1.85
4.5	410	1.4	306.6	"	"	10000	—	5.3	350	1.65
3.5	530	1.1	390.2	"	"	10000	—	4.2	440	1.35
3.0	610	0.98	457.3	"	"	10000	—	3.6	500	1.2
2.6	700	0.86	539.3	"	"	10000	—	3.1	590	1.0
6.9	305	2.3	197.1	BS40Z-../D07LA4	70	15000	—	8.3	255	2.7
5.5	325	2.8	249.6	"	"	15000	—	6.5	275	3.3
4.7	450	1.6	287.7	"	"	15000	—	5.7	370	1.95
4.5	400	2.7	302.1	"	"	15000	—	5.4	330	3.2
3.8	470	2.3	356.8	"	"	15000	—	4.6	390	2.8
3.1	580	1.7	446.8	"	"	15000	—	3.7	485	2.0
2.6	690	1.6	520.8	"	"	15000	—	3.2	560	1.95
2.3	750	1.2	612.1	"	"	15000	—	2.7	640	1.4
1.9	900	0.84	736.5	"	"	15000	—	2.2	780	0.97

P = 0.37 кВт

295	10.5	1.45	4.60	BS02-../D07LA4	9.3	450	—	355	8.7	1.7
250	12.4	1.6	5.40	"	"	510	—	300	10.3	1.95
200	15.1	1.65	6.75	"	"	590	—	240	12.6	2.0
164	18	1.4	8.25	"	"	600	—	197	15	1.65
127	22.5	1.1	10.67	"	"	600	—	152	19	1.3
100	27.5	0.91	13.50	"	"	600	—	120	22.5	1.1
100	27.5	2.0	13.50	BS03-../D07LA4	9.4	800	—	120	22.5	2.4
72	37	1.5	19.00	"	"	800	—	86	31	1.75
54	45	1.2	25.00	"	"	800	—	65	37.5	1.45
41	52	1.05	33.00	"	"	800	—	49.5	43.5	1.25


P = 0.37 кВт



Danfoss

50 Гц			i	Тип	m, кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
35	64	0.86	39.00	BS03-../D07LA4	9.4	800	—	42	53	1.05
152	18.1	1.65	8.93	BS04-../D07LA4	9.8	1000	—	182	15.1	2.0
126	21.5	1.5	10.73	"	"	1000	—	151	18.2	1.75
104	26	1.25	13.09	"	"	1000	—	124	21.5	1.55
83	32.5	1.1	16.31	"	"	1000	—	100	27	1.3
65	41	0.9	20.96	"	"	1000	—	78	34	1.1
152	18.8	3.3	8.93	BS06-../D07LA4	14	1710	—	182	15.7	3.9
126	22.5	2.9	10.73	"	"	1850	—	151	18.9	3.4
96	29.5	2.3	14.07	"	"	2000	—	116	24.5	2.8
82	34	2.1	16.56	"	"	2000	—	98	28.5	2.5
69	40.5	1.85	19.82	"	"	2000	—	82	34	2.2
56	50	1.55	24.25	"	"	2000	—	67	42	1.85
52	49.5	1.55	26.21	"	"	2000	—	62	41.5	1.85
43	59	1.35	31.50	"	"	2000	—	52	49.5	1.6
33	77	1.1	41.29	"	"	2000	—	39.5	64	1.35
28	90	0.98	48.60	"	"	2000	—	33.5	75	1.15
23.5	106	0.86	58.15	"	"	2000	—	28	89	1.0
63	44.5	2.8	21.61	BS10-../D07LA4	26	3000	—	75	37.5	3.3
52	53	2.5	26.42	"	"	3250	—	62	44	3.0
40.5	66	2.0	33.55	"	"	3550	—	48.5	55	2.5
34	77	1.8	39.96	"	"	3800	—	41	64	2.2
28.5	92	1.6	47.59	"	"	4050	—	34.5	76	1.9
24	108	1.4	57.12	"	"	4350	—	28.5	91	1.65
22.5	105	1.45	60.74	"	"	4550	—	27	87	1.7
19	137	1.15	71.96	"	"	5000	—	23	113	1.4
16.5	158	0.95	84.36	"	"	5300	—	19.5	134	1.1
13.5	167	0.96	103.4	"	"	5600	—	16	141	1.15
32.5	82	3.3	42.08	BS20-../D07LA4	36	5200	—	38.5	69	3.9
28	94	2.9	48.98	"	"	5500	—	33.5	79	3.4
27	87	3.1	50.44	"	"	5700	—	32.5	72	3.8
23	115	2.4	58.74	"	"	5900	—	28	94	3.0
19.5	135	2.2	70.30	"	"	6300	—	23.5	112	2.7
18	129	2.1	76.18	"	"	6600	—	21.5	108	2.5
15.5	150	1.8	88.67	"	"	7000	—	18.5	126	2.1
13.5	193	1.3	101.1	"	"	7100	—	16.5	158	1.6
13	179	1.5	106.3	"	"	7600	—	15.5	150	1.8
11	210	1.3	127.3	"	"	8000	—	13	179	1.5
8.5	270	1.0	159.4	"	"	8000	—	10.5	220	1.25
7.4	315	0.89	183.0	"	"	8000	—	8.9	260	1.1
6.8	330	0.85	201.4	BS20Z-../D07LA4	38	8000	—	8.1	275	1.0
16.5	164	2.5	83.48	BS30-../D07LA4	54	6800	—	19.5	139	2.9
15	162	3.0	90.59	"	"	7700	—	18	135	3.6
13	184	2.8	106.2	"	"	8200	—	15.5	155	3.3
11	215	2.4	125.2	"	"	8700	—	13	184	2.8
9.0	260	2.1	151.1	"	"	9500	—	11	215	2.5
7.3	315	1.7	186.7	"	"	10000	—	8.7	265	2.0
6.3	370	1.4	216.4	"	"	10000	—	7.5	310	1.7
5.2	445	1.25	261.6	BS30Z-../D07LA4	56	10000	—	6.2	375	1.5
4.5	510	1.15	306.6	"	"	10000	—	5.3	430	1.35
3.5	650	0.91	390.2	"	"	10000	—	4.2	540	1.1
3.0	750	0.8	457.3	"	"	10000	—	3.6	620	0.97
6.9	375	1.85	197.1	BS40Z-../D07LA4	70	15000	—	8.3	315	2.2
5.5	400	2.3	249.6	"	"	15000	—	6.5	340	2.6
4.7	550	1.3	287.7	"	"	15000	—	5.7	455	1.55
4.5	490	2.2	302.1	"	"	15000	—	5.4	410	2.6

P = 0.37 кВт




Danfoss

50 Гц			i	Тип	m, кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
3.8	580	1.85	356.8	BS40Z-../D07LA4	70	15000	—	4.6	480	2.3
3.1	710	1.4	446.8	"	"	15000	—	3.7	600	1.65
2.6	850	1.3	520.8	"	"	15000	—	3.2	690	1.6
2.3	930	0.98	612.1	"	"	15000	—	2.7	790	1.15

P = 0.55 кВт

305	15.1	2.6	4.60	BS03-../D08MA4	10	600	—	370	12.4	3.2
235	19.6	2.2	6.00	"	"	730	—	280	16.5	2.7
175	25.5	1.9	8.00	"	"	800	—	210	21.5	2.2
140	31.5	1.65	10.00	"	"	800	—	168	26	2.0
104	39	1.4	13.50	"	"	800	—	125	32.5	1.7
74	53	1.05	19.00	"	"	800	—	89	44.5	1.25
56	64	0.86	25.00	"	"	800	—	68	53	1.05
157	27	2.3	8.93	BS06-../D08MA4	16	1710	—	189	22.5	2.8
131	32	2.0	10.73	"	"	1850	—	157	27	2.4
100	42.5	1.6	14.07	"	"	2000	—	120	35	1.95
85	49	1.45	16.56	"	"	2000	—	102	41	1.75
71	59	1.25	19.82	"	"	2000	—	85	49	1.55
58	72	1.05	24.25	"	"	2000	—	70	60	1.3
54	71	1.1	26.21	"	"	2000	—	65	58	1.35
44.5	86	0.93	31.50	"	"	2000	—	54	71	1.15
83	50	2.4	16.92	BS10-../D08MA4	27	2700	—	100	42	2.9
65	64	1.95	21.61	"	"	3000	—	78	53	2.4
53	77	1.7	26.42	"	"	3250	—	64	64	2.0
46	78	1.65	30.63	"	"	3550	—	55	65	2.0
42	95	1.4	33.55	"	"	3550	—	51	78	1.75
35.5	110	1.25	39.96	"	"	3800	—	42.5	92	1.5
29.5	133	1.1	47.59	"	"	4050	—	35.5	110	1.3
25	155	0.97	57.12	"	"	4350	—	29.5	131	1.15
23.5	149	1.0	60.74	"	"	4550	—	28	125	1.2
19.5	199	0.8	71.96	"	"	5000	—	23.5	165	0.97
51	80	3.1	27.86	BS20-../D08MA4	37	4450	—	61	67	3.7
46	82	3.0	30.63	"	"	4750	—	55	68	3.7
43	94	2.9	32.87	"	"	4750	—	52	77	3.5
35	108	2.4	40.25	"	"	5300	—	42	90	2.9
33.5	119	2.3	42.08	"	"	5200	—	40	99	2.7
29	135	2.0	48.98	"	"	5500	—	34.5	114	2.4
28	125	2.2	50.44	"	"	5700	—	33.5	105	2.6
24	164	1.7	58.74	"	"	5900	—	29	135	2.1
20	196	1.55	70.30	"	"	6300	—	24	164	1.85
18.5	187	1.45	76.18	"	"	6600	—	22.5	154	1.75
16	215	1.25	88.67	"	"	7000	—	19	182	1.5
14	275	0.91	101.1	"	"	7100	—	17	225	1.1
13.5	255	1.05	106.3	"	"	7600	—	16	215	1.25
11	315	0.86	127.3	"	"	8000	—	13.5	255	1.05
28	144	3.1	50.04	BS30-../D08MA4	55	5900	—	34	118	3.8
24	168	2.7	58.64	"	"	6900	—	29	139	3.3
20	183	2.6	71.17	"	"	7000	—	24	153	3.1
17	235	1.75	83.48	"	"	6800	—	20.5	197	2.1
15.5	230	2.1	90.59	"	"	7700	—	19	190	2.6
13.5	260	1.95	106.2	"	"	8200	—	16	220	2.3
11.5	310	1.7	125.2	"	"	8700	—	13.5	260	2.0
9.3	375	1.45	151.1	"	"	9500	—	11.5	305	1.75
7.5	460	1.2	186.7	"	"	10000	—	9.0	385	1.4
6.5	530	0.98	216.4	"	"	10000	—	7.8	440	1.2

P = 0.55 кВт




Danfoss

50 Гц			i	Тип	m, кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
5.4	640	0.88	261.6	BS30Z-../D08MA4	58	10000	—	6.5	530	1.05
11.5	305	3.2	126.0	BS40-../D08MA4	68	14900	—	13.5	260	3.8
9.5	355	2.7	148.1	"	"	15000	—	11.5	295	3.3
7.9	430	1.9	178.2	"	"	15000	—	9.5	355	2.3
6.4	510	1.55	219.7	"	"	15000	—	7.7	425	1.85
5.7	580	1.55	249.6	BS40Z-../D08MA4	71	15000	—	6.8	485	1.85
4.9	790	0.91	287.7	"	"	15000	—	5.9	650	1.1
4.7	700	1.55	302.1	"	"	15000	—	5.6	590	1.8
4.0	820	1.3	356.8	"	"	15000	—	4.8	680	1.6
3.2	1030	0.96	446.8	"	"	15000	—	3.8	870	1.15
2.7	1220	0.9	520.8	"	"	15000	—	3.3	1000	1.1

P = 0.75 кВт

305	20.5	1.95	4.60	BS03-../D08LA4	12	600	—	370	17	2.4
235	26.5	1.65	6.00	"	"	730	—	280	22.5	1.95
175	35	1.35	8.00	"	"	800	—	210	29	1.65
140	42.5	1.2	10.00	"	"	800	—	168	35.5	1.45
104	53	1.05	13.50	"	"	800	—	125	44.5	1.25
157	36.5	1.7	8.93	BS06-../D08LA4	17	1710	—	189	30.5	2.0
131	44	1.5	10.73	"	"	1850	—	157	36.5	1.8
100	58	1.15	14.07	"	"	2000	—	120	48	1.4
85	67	1.05	16.56	"	"	2000	—	102	56	1.3
71	80	0.94	19.82	"	"	2000	—	85	67	1.1
54	96	0.8	26.21	"	"	2000	—	65	80	0.96
83	69	1.75	16.92	BS10-../D08LA4	29	2700	—	100	57	2.1
65	88	1.4	21.61	"	"	3000	—	78	73	1.7
53	105	1.25	26.42	"	"	3250	—	64	87	1.5
46	107	1.2	30.63	"	"	3550	—	55	89	1.45
42	129	1.05	33.55	"	"	3550	—	51	106	1.25
35.5	151	0.93	39.96	"	"	3800	—	42.5	126	1.1
29.5	182	0.8	47.59	"	"	4050	—	35.5	151	0.96
83	69	3.2	16.92	BS20-../D08LA4	39	3700	—	100	58	3.8
63	92	2.5	22.23	"	"	4100	—	76	76	3.0
51	109	2.3	27.86	"	"	4450	—	61	91	2.7
46	112	2.2	30.63	"	"	4750	—	55	93	2.7
43	128	2.1	32.87	"	"	4750	—	52	106	2.5
35	147	1.75	40.25	"	"	5300	—	42	122	2.1
33.5	162	1.65	42.08	"	"	5200	—	40	136	2.0
29	185	1.45	48.98	"	"	5500	—	34.5	155	1.75
28	171	1.6	50.44	"	"	5700	—	33.5	143	1.9
24	220	1.25	58.74	"	"	5900	—	29	185	1.5
20	265	1.15	70.30	"	"	6300	—	24	220	1.35
18.5	255	1.05	76.18	"	"	6600	—	22.5	210	1.3
16	295	0.92	88.67	"	"	7000	—	19	245	1.1
42	139	3.0	33.55	BS30-../D08LA4	56	5200	—	51	115	3.7
37	145	2.9	37.92	"	"	5500	—	44.5	120	3.5
36	161	2.7	39.31	"	"	5500	—	43	134	3.2
28	196	2.3	50.04	"	"	5900	—	34	162	2.8
24	225	2.0	58.64	"	"	6900	—	29	190	2.4
20	250	1.9	71.17	"	"	7000	—	24	205	2.3
17	320	1.3	83.48	"	"	6800	—	20.5	265	1.55
15.5	315	1.55	90.59	"	"	7700	—	19	260	1.9
13.5	360	1.4	106.2	"	"	8200	—	16	300	1.7
11.5	420	1.25	125.2	"	"	8700	—	13.5	360	1.45

P = 0.75 кВт




Danfoss

50 Гц			i	Тип	m, кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
9.3	510	1.05	151.1	BS30-../D08LA4	56	9500	—	11.5	415	1.3
7.5	630	0.86	186.7	"	"	10000	—	9.0	520	1.05
20.5	265	2.8	69.60	BS40-../D08LA4	69	11800	—	24.5	225	3.3
19.5	255	3.5	73.09	"	"	12100	—	23	215	4.1
16.5	295	3.1	86.33	"	"	12900	—	19.5	250	3.6
13	365	2.6	108.1	"	"	14000	—	16	295	3.2
11.5	415	2.4	126.0	"	"	14900	—	13.5	355	2.8
9.5	490	2.0	148.1	"	"	15000	—	11.5	400	2.4
7.9	580	1.4	178.2	"	"	15000	—	9.5	490	1.65
6.4	700	1.15	219.7	"	"	15000	—	7.7	580	1.35
5.7	790	1.15	249.6	BS40Z-../D08LA4	73	15000	—	6.8	660	1.35
4.7	960	1.1	302.1	"	"	15000	—	5.6	800	1.35
4.0	1120	0.96	356.8	"	"	15000	—	4.8	940	1.15

P = 1.1 кВт

83	101	1.2	16.92	BS10-../D09SA4	32	2700	—	100	84	1.45
65	129	0.97	21.61	"	"	3000	—	78	107	1.15
53	154	0.84	26.42	"	"	3250	—	64	128	1.0
46	157	0.83	30.63	"	"	3550	—	55	131	0.99
83	102	2.2	16.92	BS20-../D09SA4	43	3700	—	100	85	2.6
63	135	1.7	22.23	"	"	4100	—	76	111	2.1
51	160	1.55	27.86	"	"	4450	—	61	134	1.85
46	164	1.5	30.63	"	"	4750	—	55	137	1.8
43	188	1.45	32.87	"	"	4750	—	52	155	1.75
35	215	1.2	40.25	"	"	5300	—	42	180	1.45
33.5	235	1.15	42.08	"	"	5200	—	40	199	1.35
29	270	1.0	48.98	"	"	5500	—	34.5	225	1.2
28	250	1.1	50.44	"	"	5700	—	33.5	210	1.3
24	325	0.86	58.74	"	"	5900	—	29	270	1.05
67	130	2.9	20.94	BS30-../D09SA4	60	4300	—	81	107	3.6
52	167	2.4	27.07	"	"	4750	—	63	138	2.9
46	171	2.3	30.63	"	"	5000	—	55	143	2.8
42	205	2.0	33.55	"	"	5200	—	51	168	2.5
37	210	2.0	37.92	"	"	5500	—	44.5	177	2.4
36	235	1.85	39.31	"	"	5500	—	43	197	2.2
28	285	1.6	50.04	"	"	5900	—	34	235	1.9
24	335	1.35	58.64	"	"	6900	—	29	275	1.65
20	365	1.3	71.17	"	"	7000	—	24	305	1.55
17	475	0.86	83.48	"	"	6800	—	20.5	390	1.05
15.5	465	1.05	90.59	"	"	7700	—	19	380	1.3
13.5	520	0.98	106.2	"	"	8200	—	16	445	1.15
11.5	620	0.84	125.2	"	"	8700	—	13.5	520	1.0
29.5	275	3.0	47.69	BS40-../D09SA4	73	9600	—	35.5	230	3.6
23.5	315	2.7	60.38	"	"	11200	—	28	265	3.2
20.5	390	1.9	69.60	"	"	11800	—	24.5	330	2.3
19.5	375	2.3	73.09	"	"	12100	—	23	315	2.8
16.5	435	2.1	86.33	"	"	12900	—	19.5	370	2.4
13	540	1.75	108.1	"	"	14000	—	16	435	2.2
11.5	610	1.6	126.0	"	"	14900	—	13.5	520	1.9
9.5	710	1.35	148.1	"	"	15000	—	11.5	590	1.65
7.9	860	0.95	178.2	"	"	15000	—	9.5	710	1.15

P = 1.5 кВт




Danfoss

50 Гц			i	Тип	m , кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
83	138	0.87	16.92	BS10-../D09LA4	36	2700	—	100	114	1.05
83	139	1.6	16.92	BS20-../D09LA4	47	3700	—	100	116	1.9
63	184	1.25	22.23	"	"	4100	—	76	152	1.5
51	215	1.15	27.86	"	"	4450	—	61	183	1.35
46	220	1.15	30.63	"	"	4750	—	55	187	1.35
43	255	1.05	32.87	"	"	4750	—	52	210	1.3
35	290	0.9	40.25	"	"	5300	—	42	245	1.05
33.5	320	0.84	42.08	"	"	5200	—	40	270	1.0
83	143	2.5	16.92	BS30-../D09LA4	64	3950	—	100	118	3.1
67	177	2.1	20.94	"	"	4300	—	81	146	2.6
52	225	1.8	27.07	"	"	4750	—	63	188	2.1
46	230	1.75	30.63	"	"	5000	—	55	195	2.1
42	275	1.55	33.55	"	"	5200	—	51	230	1.85
37	290	1.45	37.92	"	"	5500	—	44.5	240	1.75
36	320	1.35	39.31	"	"	5500	—	43	265	1.6
28	390	1.15	50.04	"	"	5900	—	34	320	1.4
24	455	1.0	58.64	"	"	6900	—	29	380	1.2
20	500	0.96	71.17	"	"	7000	—	24	415	1.15
46	230	3.3	30.63	BS40-../D09LA4	77	8700	—	55	192	3.9
42	270	2.9	33.35	"	"	8300	—	51	220	3.5
37	280	2.8	38.13	"	"	9400	—	44.5	230	3.4
35	320	2.5	40.37	"	"	9000	—	42	265	3.0
29.5	375	2.2	47.69	"	"	9600	—	35.5	310	2.7
23.5	430	2.0	60.38	"	"	11200	—	28	360	2.4
20.5	530	1.4	69.60	"	"	11800	—	24.5	450	1.65
19.5	510	1.75	73.09	"	"	12100	—	23	435	2.0
16.5	590	1.55	86.33	"	"	12900	—	19.5	500	1.8
13	730	1.3	108.1	"	"	14000	—	16	590	1.6
11.5	830	1.2	126.0	"	"	14900	—	13.5	710	1.4
9.5	980	0.99	148.1	"	"	15000	—	11.5	800	1.2

P = 2.2 кВт

83	205	1.05	16.92	BS20-../D09XA4	51	3700	—	100	170	1.3
63	270	0.85	22.23	"	"	4100	—	76	220	1.05
83	210	1.7	16.92	BS30-../D09XA4	68	3950	—	100	174	2.1
67	260	1.45	20.94	"	"	4300	—	81	215	1.75
52	335	1.2	27.07	"	"	4750	—	63	275	1.45
46	340	1.2	30.63	"	"	5000	—	55	285	1.4
42	410	1.0	33.55	"	"	5200	—	51	335	1.25
37	425	0.99	37.92	"	"	5500	—	44.5	350	1.2
36	470	0.91	39.31	"	"	5500	—	43	395	1.1
83	215	3.1	16.92	BS40-../D09XA4	81	6400	—	100	178	3.8
67	255	2.8	21.06	"	"	6900	—	80	215	3.3
54	315	2.3	26.18	"	"	7500	—	65	265	2.8
46	335	2.2	30.63	"	"	8700	—	55	280	2.7
42	400	1.95	33.35	"	"	8300	—	51	325	2.4
37	410	1.9	38.13	"	"	9400	—	44.5	340	2.3
35	470	1.7	40.37	"	"	9000	—	42	395	2.0
29.5	550	1.5	47.69	"	"	9600	—	35.5	460	1.8
23.5	630	1.35	60.38	"	"	11200	—	28	530	1.6
20.5	780	0.95	69.60	"	"	11800	—	24.5	660	1.15
19.5	750	1.15	73.09	"	"	12100	—	23	630	1.4
16.5	870	1.05	86.33	"	"	12900	—	19.5	740	1.2
13	1080	0.88	108.1	"	"	14000	—	16	870	1.1

P = 2.2 кВт



Danfoss

50 Гц			i	Тип	m, кг	F _{RN} , Н	F _{RV} , Н	60 Гц		
n ₂ , 1/мин	M ₂ , Нм	f _B						n ₂ , 1/мин	M ₂ , Нм	f _B
11.5	1220	0.8	126.0	BS40-../D09XA4	81	14900	—	13.5	1040	0.94

P = 3.0 кВт

84	285	2.4	16.92	BS40-../D11SA4	89	6400	—	102	235	2.9
68	345	2.1	21.06	"	"	6900	—	82	285	2.5
55	425	1.75	26.18	"	"	7500	—	66	355	2.1
46.5	455	1.65	30.63	"	"	8700	—	56	375	2.0
43	530	1.45	33.35	"	"	8300	—	52	440	1.75
37.5	550	1.4	38.13	"	"	9400	—	45	460	1.7
35.5	630	1.25	40.37	"	"	9000	—	42.5	530	1.5
30	740	1.1	47.69	"	"	9600	—	36	620	1.35
24	840	1.0	60.38	"	"	11200	—	28.5	710	1.2
19.5	1020	0.86	73.09	"	"	12100	—	23.5	850	1.05

P = 4.0 кВт

84	385	1.75	16.92	BS40-../D11MA4	95	6400	—	102	315	2.1
68	460	1.55	21.06	"	"	6900	—	82	380	1.85
55	560	1.3	26.18	"	"	7500	—	66	470	1.55
46.5	600	1.25	30.63	"	"	8700	—	56	500	1.5
43	710	1.1	33.35	"	"	8300	—	52	580	1.35
37.5	740	1.05	38.13	"	"	9400	—	45	610	1.3
35.5	850	0.94	40.37	"	"	9000	—	42.5	710	1.15
30	990	0.84	47.69	"	"	9600	—	36	820	1.0

P = 5.5 кВт

84	530	1.25	16.92	BS40-../D11LA4	107	6400	—	102	435	1.55
68	630	1.15	21.06	"	"	6900	—	82	520	1.35
55	780	0.95	26.18	"	"	7500	—	66	650	1.15
46.5	830	0.9	30.63	"	"	8700	—	56	690	1.1
43	970	0.8	33.35	"	"	8300	—	52	800	0.98